



HOW OUR MACHINE MONITORING WORKS





Tablets mounted to individual

machines display job performance and

reject parts, and indicate tool changes.

provide operators a simple interface

to make the machine data smarter:

Categorize downtime, track setup,

Real-TimeDashboards

This Transparency immediately increases efficiency 10%

TV Monitors on the shop floor display the performance of jobs against their goals. Each tile represents one machine and are color-coded so staff can identify machines that are underperforming and quickly correct any problems.

Historical Reporting

Plant managers can use MachineMetrics robust OEE reporting and analytics capabilities to measure and improve machine utilization and productivity.

View factory data on the go with mobile views for all reports and dashboards.





Increase Production By at Least 10%

With new data transparency you can improve quoting by knowing actual cycle times, increase machine capacity by better understanding downtime due to inspection, maintenance, and setup. Ensure on-time delivery by knowing when a work order is likely to be completed.

