



www.machinmetrics.com

413-341-5747

Title: *CONNECTION DIAGRAM*
Example for Haas Serial using
MOXA NPort Kit

Notes:
1. Plug into standard 115vac duplex receptacle.
2. Use supplied 3M adhesive to mount device to outside of enclosure. Clean surface before applying.

Created by: *C.Shaffer*

Revised by: *--*

ANSI Size: *D*

File Name: *CD-MOXA-KIT_20201020.dwg*

Creation Date: *2020/10/20*

Revision Date: *Initial Release*

Scale: *1:1*

Rev No.

--

Page:

01 of 01